

No. 11253

RECEIVED FROM

2961 E. COLORADO ST., PASADENA, CALIF.

PLANT #9

DATE REC'D. 2-12-57

P.O. NO.

VENDOR PACKING SLIP NO.

CONTRACT CODE NO.

DRAWING NUMBER

DWG. DASH OR STANDARD PART NO.

DWG. REV.

LOT NO.

CLASS NUMBER

OPER. NUMBER

BUY OUT CODE NO.

Q

R

ACCT. OR W.O. NO.

S.O. NO.

CHARGE TO QUANTITY RECEIVED

322

04

0

10

DRAWING NO. AND DESCRIPTION

QUANTITY

ACCEPTED

REJECTED

REMARKS

3

731441 Barnes Assembly

Shipper 3592

3

✓

*[Handwritten signature]*  
*[Handwritten signature]*

RECEIVED BY

INSPECTED BY

*[Handwritten signature]*

DATE

2/12/57

REJECTS RETURNED ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11254

RECEIVED FROM

PLANT #9

DATE REC'D. 2-12-57

P.O. NO.

VENDOR PACKING SLIP NO.

CONTRACT CODE NO.

DRAWING NUMBER

DWG. DASH OR STANDARD PART NO.

DWG. REV.

LOT NO.

CLASS NUMBER

OPER. NUMBER

BUY OUT CODE NO.

Q

R

ACCT. OR W.O. NO.

S.O. NO.

CHARGE TO QUANTITY RECEIVED

322

24

0

10

DRAWING NO. AND DESCRIPTION

QUANTITY

ACCEPTED

REJECTED

REMARKS

3

731341 Socket Plate Chamber

Shipper 3592

3

✓

✗

~~Ret 3534~~

*[Handwritten signature]*  
*[Handwritten signature]*

RECEIVED BY

INSPECTED BY

*[Handwritten signature]*

DATE

2/12/57

REJECTS RETURNED ON SHIP. MEMO NO.